AMENDMENT TO APPENDIX TO STORMWATER MANAGEMENT PLAN OF WASHINGTON COUNTY, ARKANSAS

Maintenance Requirements

Inlet protection measures should be inspected during storm events to ensure surrounding facilities are not flooded.

Inlet protection measures should be inspected bi- weekly and after one-half (1/2) inch or greater rainfalls for proper installation, defective fencing, erosion, and excessive sediment buildup; and defective measures repaired or replaced within twenty-four (24) hours repair or replacement of defective measures must be initiated within twenty-four hours of discovery and completed in no less than seven (7) days from discovery.

Maintenance Requirements

Sediment Traps should be inspected bi- weekly and after one-half (1/2) inch or greater rainfalls for proper installation, erosion, and excessive sediment buildup; and defective measures repaired or replaced within twenty four (24) hours repair or replacement of defective measures must be initiated within twenty-four (24) hours of discovery and completed in no less than seven (7) days from discovery.

Maintenance Requirements

Check Dams should be inspected bi- weekly and after one-half (1/2) inch or greater rainfalls for proper installation, erosion, and excessive sediment buildup; and defectives should be repaired or replaced within twenty four (24) hours repair or replacement of defective measures must be initiated within twenty-four (24) hours of discovery and completed in no less than seven (7) days from discovery.

ROBYN REED. Environmental Affairs Officer